Records

- 1. Radioactive Material Receipt, Use & Transfer 5 Years
- 2. Waste Disposal until License is terminated
- 3. Radiation Survey 3 years
- 4. Radiation surveys used to determine dose from external sources until license is terminated
- 5. Radiation surveys used to determine individual intakes until license is terminated
- 6. Air surveys performed during use of respiratory protection until license is terminated
- 7. Surveys used to determine release to the environment until license is terminated
- 8. Radioactive Materials Inventory **5 years**
- 9. Survey Meter Calibration 3 years
- 10. Leak Tests of Sealed Sources **5 years**
- 11. Personnel Monitoring until license is terminated
- 12. Radiation Safety Instruction until license is terminated
- 13. Recent training until license is terminated

When license is terminated, these records must be transferred to the Radiation Safety Program for permanent retention.